

# FIRE RESISTANT TIMBER DOOR SCHEME

### Certificate number: IFCC 1824

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

# TSIGENIS AEVE T/A TSIGENIS WOODCRAFT

5km Heraklion - Finikia Heraklion 71500 Greece

Tel: +302810373370

Who fabricate the following timber fire doors and or doorsets:

# Sauerland EI60

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **EN 1634-1**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes integrity and insulation** are detailed on page 2 of this certificate.



Initial certification: 22 February 2023 Valid to: 21 February 2024 Issue status: 1



175

Ian Woodhouse Head of Technical – IFC Certification

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.



IFC Certification Ltd, Ground Floor, Building 2, Bear Brook Office Park, Walton Street, Aylesbury, HP21 7GQ, UK
Tel: +44 (0)1844 276920 E-mail: <a href="mailto:uk.info@kiwa.com">uk.info@kiwa.com</a> Web: <a href="https://www.ifccertification.com">www.ifccertification.com</a>
Registered No: 4777898 England

#### Certificate number: IFCC 1824

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

<b>Doorset Description</b>	Fire Rating	Assessment/ Test Report
42 VT Doorset (Doorset 2 only)	EI60	DMT_DO_50_776_R1

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.